


Dept. of Environmental
Protection
OCT 04 2006
Southwest District

Response to September 14, 2006 Comments
Countryside Executive Golf Course
2506 Countryside Boulevard
Clearwater, Florida
HSA Project Number 601-5982-00



October 4, 2006

Florida Department of Environmental Protection
Southwest District
13051 North Telecom Parkway
Temple Terrace, Florida 33637-0926

Attention: *Mr. Robert Sellers, CHMM*
Environmental Specialist II

Subject: **Response to September 14, 2006 FDEP Comments**
Countryside Executive Golf Course
2506 Countryside Blvd.
Clearwater, Florida
HSA Project Number 601-5982-00

FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
OCT - 4 2006
SOUTHWEST DISTRICT
TAMPA

Dear Mr. Sellers:

HSA Engineers & Scientists (HSA), on behalf of Beazer Homes, respectfully submits this response to the Florida Department of Environmental Protection (FDEP) September 14, 2006, correspondence that provided comments to the July 10, 2006, *Site Assessment Report Addendum*, and the July 2006, *Interim Source Removal Plan and Groundwater Monitoring Plan* prepared by HSA, for the above-referenced site. These responses are being submitted in anticipation of a meeting between representatives of Beazer Homes and the Department scheduled for October 13, 2006. For ease of review, the Department's comments are presented below, followed by HSA's responses.

GROUNDWATER

Comment 1: *The Report states that the high concentrations of arsenic at MW-2 will attenuate naturally over time. The fluctuations in arsenic concentrations would appear to indicate that natural attenuation is not occurring at this location. Arsenic concentrations increased from 37.3 µg/L to 79.8 µg/L between May 30, 2006 and June 13, 2006.*

Response: Monitoring well MW-2 was initially sampled in August 2005 and was re-sampled in November 2005, May 2006, and June 2006. The arsenic results were reported at concentrations of 119 µg/L, 130 µg/L, 37.3 µg/L, and 79.8 µg/L, respectively.


www.hsa-env.com

Environmental & Geotechnical Engineering • Construction Materials Testing

4019 East Fowler Avenue / Tampa, Florida 33617-2008

Tel: (813)971-3882 / Fax: (813)971-1862

Offices in: Tampa • Ft. Lauderdale • Ft. Myers • Cape Canaveral • West Palm Beach • Hilton Head • Savannah • Biloxi



Although the most recent results collected in June 2006 indicate an increase in arsenic concentrations from the previous sampling performed in May 2006, the most recent result is well below historical levels of 119 $\mu\text{g/L}$ and 130 $\mu\text{g/L}$, as reported in 2005. Based upon the overall decrease in groundwater concentrations observed during nearly one year of monitoring, it appears that periodic minor fluctuations in concentrations occur, however, the general trend in concentrations indicates an overall decrease consistent with natural attenuation.

As discussed previously, monitoring wells TW-14 and TW-15 were installed to the northeast and southeast, respectively, of monitoring well MW-2 to determine whether documented arsenic impacts above the GCTL were migrating in the southeast direction toward the property line. The results of groundwater sampling at these wells in June 2006, indicated below detectable levels for arsenic.

In order to further evaluate groundwater quality in the vicinity of monitoring well MW-2, HSA proposes to install one additional groundwater monitoring well (TW-17) to the west of MW-2 as depicted in the attached **Figures 1A and 1B**. The monitoring well will be installed to a total depth of approximately 12 feet below land surface (ft bls) and will be screened from 2 to 12 ft bls. Following installation, TW-17, along with monitoring wells MW-2, TW-14, TW-15, and TW-16 will be sampled for fixed laboratory analysis for the presence of arsenic. In addition, all of the available monitoring wells located throughout the subject site will be surveyed to a relative top-of-casing elevation and the overall groundwater flow direction at the site will be confirmed.

APPROPRIATE SOIL SAMPLING WITHIN THE PROPERTY

Comment 1: *Soil isoconcentration maps of arsenic by depth are needed to indicate where the site has been delineated.*

Response: As discussed during a recent teleconference between Department and Beazer Homes representatives, the use of isoconcentration maps for delineation purposes is of limited value at the subject site because of the size of the subject site and the widespread application of arsenic-containing pesticides and/or herbicides to on-site soils. Furthermore, variations in arsenic concentrations are expected because of the expected varying capacity of soil to sorb arsenic.

In lieu of soil isoconcentration maps, site plans depicting arsenic concentrations at varying depths across the site were prepared. In accordance with requirements



included under Chapter 62-780, Florida Administrative Code (FAC), soil arsenic impacts were evaluated for depths ranging from land surface to 6-inches bls (Figure 2), 6-inches to 2 feet bls (Figure 3), 2 to 4 ft bls (Figure 4), and 4 to 6 ft bls (Figure 5). The depth to groundwater across the site is approximately 4 to 6 ft bls.

As expected, the concentrations of arsenic in soil decrease significantly with depth. Land surface to 6-inch bls samples revealed concentrations that varied from below detectable levels to 20.9 milligrams per kilogram (mg/kg) for areas outside of the maintenance facility. Within the 6-inch to 2 ft bls samples, the concentrations ranged from below detectable levels to 6.26 mg/kg. For the 2 to 4 ft bls samples, the results range from below detectable levels to 5.23 mg/kg at all locations with the exception of SS-7. At SS-7, the exhibited concentration of arsenic was 12.7 mg/kg. Because the shallow samples at this location resulted in concentrations of below detectable levels and 1.11 mg/kg, the 2 to 4 ft bls result appears to be anomalous. HSA recommends re-sampling to confirm previous results. In summary, 9 of the 10 samples gathered from land surface to 6-inches bls exceed the residential SCTL, 2 of the 10 samples gathered from 6 inches bls to 2 ft bls exceed the residential SCTL, and 3 of the 10 samples gathered from 2 to 4 ft bls exceed the residential SCTL.

Comment 2: *Soil samples at depths greater than 6 inches are needed to rule out a persistent source area for the arsenic at the MW-2 location. The report stated that this area might have been used as a temporary maintenance area. Soil samples from this area should also be analyzed for arsenic, pesticides, and herbicides using the Synthetic Precipitation Leaching Procedure (Method 1312). Samples that did not exceed the SCTL at the 0-2-foot interval may exceed the residential SCTL in the upper 6 inches.*

Response: Four soil samples were gathered from the vicinity of monitoring well MW-2 in May 2006. The soil samples were gathered from land surface to 6-inches bls. The results indicated arsenic concentrations ranging from 3.56 to 6.63 mg/kg. In order to further evaluate the potential presence of arsenic, pesticides, and herbicides in the vicinity of monitoring well MW-2, additional soil sampling is proposed. Five soil samples are proposed in the vicinity of monitoring well MW-2 at locations depicted in Figure 1B. Soil samples will be gathered from land surface to 6-inches bls, 6-inches bls to 2 ft bls, and 2 to 4 ft bls at each location. All of the soil samples will be analyzed for the presence of arsenic. The shallow soil samples will also be analyzed for the presence of pesticides by EPA Method



8081 and herbicides by EPA Method 8151. If concentrations of pesticides and/or herbicides are detected at levels above their respective GCTLs, then the corresponding samples from the deeper intervals will be analyzed. In lieu of SPLP analysis, herbicide and pesticide concentrations will be compared to default Leachability-based SCTLs.

Comment 3: *Chapter 62-780, FAC requires that for surface releases, soil samples be collected from a depth of 0-6". Only the samples from the 2005 soil-sampling event were collected from this depth. This site does not appear to be delineated with depth.*

Response: As discussed during the recent teleconference, the shallow soil arsenic impacts that exist throughout the subject site appear to be the result of routine pesticide/herbicide application of a period of many years. Because of the size of the subject site (44 acres) and the nature of the arsenic impacts (applied as part of routine application), HSA recommends that a limited number of delineation soil samples be gathered at the property boundaries to confirm that off-site soil impacts have not occurred. A total of twelve delineation soil locations are recommended (Figure 6). At each proposed sampling location, soil samples will be gathered from land surface to 6 inches bls, 6-inches to 2 ft bls, and 2 to 4 ft bls. Soil samples will be analyzed for the presence of arsenic by EPA Method 6010. All potential for future exposure associated with arsenic in soils located on the subject site will be managed through the use of an engineering/institutional control as part of site redevelopment.

Comment 4: *It is not clear from the data if all of the greens and tees were sampled, or if a representative number of greens were sampled. Typically we see the highest concentration of contaminants on the tees and greens with lower concentrations found in the fairways. It is not clear on the maps because the sample locations do not appear to correspond to locations of the tees and greens that are seen in the aerial photographs.*

Response: To date, samples of the tees and greens has not been conducted, however soil samples have been collected adjacent to both tees and greens. In order to further evaluate the potential for arsenic soil impacts on the tees and greens, four additional soil borings are proposed at tees and greens throughout the subject site. The borings will be advanced on the tees and greens at holes 3, 6, 14, and 16 (see Figure 2 for hole locations). At each proposed sampling location, soil samples will be gathered from land surface to 6-inches bls, 6-inches to 2 ft bls, and 2 to 4



ft bls. Soil samples will be analyzed for the presence of arsenic by EPA Method 6010. It should be noted that tee and green sampling results will be evaluated to determine trends in arsenic concentrations. All potential for future exposure associated with arsenic in soils located on the subject site will be managed through the use of an engineering/institutional control as part of site redevelopment.

Comment 5: *It is not clear why the proposed interim source removal does not extend down to the area surrounding the CSS-8 soil sample location. Arsenic is present at 8.3 mg/kg at this location at the 0-2' interval. No soil samples were taken below 2' at this location and several other locations where the residential SCTL was exceeded. The area around the maintenance facility needs to be fully delineated to residential and/or leachability SCTLs as described below. The area to be excavated may need to be expanded.*

Response: See response to comment 1 under Leachability SCTL for Arsenic below.

Comment 6: *It does not appear that soil samples have been taken down to the water table. This information will be important to know, once a leachability SCTL is established (see below).*

Response: Historically, the water table beneath the subject site was determined to be between 4 and 6 ft bls. A total of six soil borings were advanced to a total depth of 16 ft bls in October 2004. A summary of the historical soil sampling arsenic analytical results is included as Table 1 and a site plan depicting the locations of the historical soil sampling locations is included as Figure 1A. Soil samples were gathered at two-foot intervals to the total depth of the boring for arsenic analysis. The results of the subsequent arsenic analysis did not identify any soil samples that exhibited arsenic concentrations above its respective SCTLs.

LEACHABILITY SCTL FOR ARSENIC

Comment 1: *SPLP testing must be conducted to establish a leachability SCTL for arsenic at the site. This will ensure that all soils with the potential to affect the groundwater at the site are removed or appropriately managed through an engineering control. A representative number of soil samples at various total arsenic concentrations need to be collected and analyzed for both SPLP and total arsenic. Using these data, a correlation curve can be constructed so that the concentration of total arsenic that is acceptable to leave in place without*



engineering controls is known (leachability SCTL). This should be done before any excavation is done so that the leachability SCTL is known and remedial actions can be planned accordingly.

Response: Pursuant to Rule 62-780.680(2)(b)2.f. (Risk Management Options-Level II), in lieu of SPLP analysis, one may demonstrate (based on a minimum of 1 year of Groundwater monitoring data) that constituents of concern (*i.e.*, arsenic) based on site-specific conditions will not leach at levels greater than applicable GCTLs. As a result, HSA recommends that leachability of arsenic in soil be evaluated and potential remedial efforts focused on the presence of groundwater impacts above the Natural Attenuation Default Source Concentration (NADSC) of 100 µg/L as established in Chapter 62-777, FAC.

In order to determine remedial objectives in the vicinity of the maintenance facility, HSA revisited the conceptual model for the subject site and evaluated soil analytical data for the vicinity of the maintenance facility and throughout the remainder of the subject site. HSA's conceptual model for the maintenance facility indicates that a discharge of arsenic occurred as a result of historical storage and mixing activities. On average, the soil concentrations near the maintenance facility are above the soil sorbtion capacity and leaching is occurring at significant rates that have resulted in associated groundwater impacts. For the remainder of the subject site, arsenic soil impacts are associated with the routine application of arsenic-containing herbicides/pesticides. Although arsenic soil impacts exist, the average soil concentration does not exceed the sorbtion capacity of soils, and therefore, does not consistently leach arsenic at elevated levels to groundwater. A summary of historical groundwater analytical data is included as Table 2 and monitoring well locations are included in Figure 7.

Based on the conceptual model, HSA recommends that a site-specific Leachability-based SCTL be conservatively determined by calculating the 95% Upper Confidence Limit (UCL) of the mean for the soils located outside of the maintenance facility (where leaching is not occurring as demonstrated by more than one year of groundwater analytical data). Assuming generally uniform soils throughout the site, this concentration can be utilized as a cleanup criteria in the vicinity of the maintenance facility to ensure that the concentrations of arsenic left in-place following excavation, do not exceed the average concentration for the remainder of the site, thereby assuring that future leaching does not occur.



In order to determine the average arsenic concentration for soils located outside of the maintenance facility, an average of all soil analytical data above the water table was utilized. For a comparative 95% UCL in the area of the maintenance facility, soil samples from boring locations P-3, CSS-32 through CSS-41, CSS-7, and CSS-51 were used. The remaining soil borings were utilized to determine site-wide average soil concentrations. The current version of PRO-UCL Version 0.97 was utilized to determine average site-wide soil concentrations in the upper 2 feet and 2 to 4 ft bls, respectively. The results of the analysis indicate a target remedial concentration for the upper 2 feet of 4.9 mg/kg. The target remedial concentration for the 2 to 4 ft bls samples was calculated to be 2.5 mg/kg. Because the target remedial concentration will be equal to or less than the Upper 95% UCL concentration over the remainder of the site (where significant leaching is not occurring), future leaching in the vicinity of the maintenance facility is not expected. For comparison, the current Upper 95% UCL in the maintenance area is 22 mg/kg from the top 2 feet and 5 mg/kg for 2 to 4 ft bls. Summaries of the 95% UCL calculations are included as **Appendix A**.

DELINEATION TO PROPERTY BOUNDARIES

Comment 1: *Many locations adjacent to off-site properties do not show delineation to the residential SCTL for arsenic. For example, CSS-2, CSS-20, SS-8, CSS-25, and CSS-31, as well as others, exceed the residential SCTL for arsenic at the 0-2 feet depth interval.*

Response: Because of the size of the subject site, comprehensive delineation of site-wide arsenic soil impacts is not practical. Nevertheless, perimeter soil sampling is proposed at several locations to confirm HSA's conceptual model for the application of arsenic-containing herbicides/pesticides at the site. As discussed above, twelve soil borings are proposed throughout the subject site adjacent to the subject property boundary (Figure 6). Soil borings will be advanced to a total depth of four ft bls. Soil samples will be gathered from land surface to 6-inches bls, 6-inches to 2 ft bls, and 2 to 4 ft bls. Each soil sample will be analyzed for the presence of arsenic by EPA Method 6010.

Comment 2: *As noted above, samples collected at the 0 – 2-foot interval that were below the SCTL may be above the SCTL at the 0 – 6-inch interval. Delineation should be done to the property boundaries.*

Response: As discussed in the previous response, soil sampling will be conducted at the property boundary.



PESTICIDES IN SOIL

Comment 1: *The Report states, "because surrounding soils are impacted with arsenic as a result of routine legal herbicide/pesticide application, confirmation sampling is not recommended". The Department does not concur with this conclusion. The Department has not adopted the EPA ruling regarding legally applied pesticides at this time. In addition, HSA has indicated that closure under Chapter 62-780 is being pursued.*

Response: To date, herbicides/pesticides have not been detected in soil or groundwater beneath the site above applicable regulatory levels. Nevertheless, herbicide and pesticide confirmation soil sampling will be conducted following source removal activities. In addition, arsenic confirmation soil sampling is also proposed (see Comment 1 under Additional Comments on the Interim Source Removal Plan below).

Comment 2: *Locations where high arsenic impacts were found were not tested for pesticides, a likely co-located contaminant.*

Response: Recent soil sampling included analyzing four soil samples in the vicinity of the maintenance facility for the presence of herbicides/pesticides. Because historical groundwater analytical data did not indicate the presence of any herbicides/pesticides above regulatory standards near the maintenance facility, recent soil sampling was focused on evaluating near surface soil quality (as the herbicide/pesticide mixing appears to have resulted in a surface release). Nevertheless, three additional soil borings are proposed to further evaluate the potential presence of herbicides/pesticides. The three soil borings will be advanced adjacent to historical soil sampling locations CSS-7, CSS-33, and CSS-40 (see **Figure 1A** for previous sampling locations). Soil samples will be gathered from land surface to 2 ft bls, 2 to 4 ft bls, and 4 to 6 ft bls for laboratory analysis for the presence of herbicides by EPA Method 8151 and pesticides by EPA Method 8081.

Comment 3: *The sampling plan for pesticides has not been justified to the Department's satisfaction. Pesticides were not tested for at any depths other than 0 – 6 inches. The reasoning behind the sampling locations is not clear, as they do not appear to correspond to potential mixing areas.*



Response: Because the highest arsenic soil concentrations were detected in the shallow depth samples and because the release near the maintenance facility is suspected to be a surface release, herbicide/pesticide sampling was conducted from land surface to 6-inches bls near the maintenance facility. As discussed above, additional herbicide/pesticide sampling is proposed at deeper depths in the vicinity of the maintenance facility and in the vicinity of monitoring well MW-2.

Comment 4: *Chapter 62-780 requires sampling down to the water table.*

Response: Acknowledged. Additional sampling will include testing down to the water table.

Comment 5: *An appropriate number of samples should be collected in the area surrounding MW-2 and analyzed for pesticides.*

Response: See response to comment 2 under Appropriate Soil Sampling within the Property.

Comment 6: *Units for the SCTLs for pesticides and herbicides in Table 3 are incorrect. They should be in mg/kg, not µg/kg.*

Response: Acknowledged. The corrected Table 3 is attached.

SURFACE WATER

Comment 1: *The Freshwater Surface Water Criteria of 50 µg/L for arsenic was exceeded at the pond located south of the maintenance area. Although a second sample (49 µg/L) from the pond indicated arsenic below the Surface Water Criteria, surface water at the pond should be re-sampled after excavation activities are complete.*

Response: Acknowledged. A surface water sample will be gathered from the pond following excavation activities. The sample will be analyzed for the presence of arsenic by EPA Method 6010.

OTHER CONCERNS

Comment 1: *Arsenic concentrations above the Department's Groundwater Cleanup Target Levels were found in public supply wells 56, 58, and 63. The Report suggests that the arsenic found in these public supply wells may be widespread and*



indicative of the local background groundwater quality. At this time, there is not enough data to support this conclusion.

Response: Acknowledged. HSA will attempt to obtain additional information regarding arsenic in groundwater at other public supply wells in the vicinity of the subject site to further confirm the presence of arsenic in the above-referenced public supply wells to be the result of local background conditions.

Comment 2: *Groundwater sampling data sheets are not all completely filled out. Among the missing information is – purge rate, purge volume, site name, decon information, filtered or not filtered, preservatives not indicated, calibration of instruments not indicated, sampler's signature, etc. FDEP SOPs should be followed.*

Response: Acknowledged. Completed groundwater sampling data sheets will be included in future reports.

Comment 3: *According to the data sheet MW-002 was purged for approximately 1.5 hours and TW012 was purged for half an hour, but no volumes were recorded.*

Response: Approximately 19 liters (5 gallons) of water was purged from monitoring well MW-2 and approximately 9 liters (2.3 gallons) of water was purged from monitoring well TW-12. Completed groundwater sampling data sheets will be included in future reports.

Comment 4: *Monitoring well completion reports are incomplete. Among information that is missing – well development data, type of well completion, top of casing, soil profile, etc.*

Response: Acknowledged. Revised well completion reports are included as Appendix B.

Comment 5: *Figure 4 in the SARA differs from Figure 3 of the SAR in regard to the locations of the irrigation wells and the City of Clearwater water supply wells. The descriptions are switched in the map legends. Please indicate the correct locations of these wells.*

Response: Figure 4 of the SARA depicts the actual locations of irrigation wells and the City of Clearwater water supply wells. The locations depicted in Figure 3 of the SAR were incorrectly located.



Comment 6: *No isoconcentration contour maps of groundwater are included. These should be included in the next SARA submittal.*

Response: Figure 3 of the Interim Source Removal Plan and Groundwater Monitoring Plan dated July 2006 included an isocontour depicting the approximate extent of arsenic in groundwater near the maintenance facility. An isocontour for the vicinity of monitoring well MW-2 is included in **Figure 1B**.

Comment 7: *No groundwater flow map for the entire site is presented. This should be included in the next SARA submittal.*

Response: Acknowledged. The next SARA will include a groundwater flow map for the entire site.

ADDITIONAL COMMENTS ON THE INTERIM SOURCE REMOVAL PLAN

Comment 1: *If excavation is done down to the water table, bottom confirmatory sampling is not required. However, sidewall confirmatory samples are required [62-780.500(5) 5].*

Response: Acknowledged. Four sidewall confirmatory samples will be gathered following excavation activities. The sidewall confirmation samples will be analyzed for the presence of arsenic by EPA Method 6010.

Comment 2: *TCLP analysis should be done on excavated soils to ensure proper disposal. [62-780.500(5) 6].*

Response: Acknowledged. TCLP analysis will be conducted during the next sampling event. Because arsenic is the only chemical of concern, arsenic TCLP analysis will be conducted.

Comment 3: *Sidewall confirmatory samples should be taken post excavation, especially in the northern portion where arsenic is present at 48 mg/kg at the 0-2' interval.*

Response: Acknowledged. Post excavation sampling will include soil sampling at the northern portion of the maintenance area.



Comment 4: *Although the proposed dimensions of the excavation are given, an estimated volume is not given for the excavation. It is also not clear that the proposed stockpile area is large enough to handle the volume (approximately 1,555 cubic yards based on the dimensions given).*

Response: During excavation, HSA will attempt to direct-load the majority of the excavated soils. Although direct-load is desired, temporarily stockpiling of a portion of the arsenic-impacted soils will likely be required. To the extent such temporary stockpiling is necessary, the proposed stockpile area is sufficient for this purpose. The location of the proposed stockpile area is included in **Figure 8**.

Comment 5: *The proposed stockpile area is reported to be on Figure 4, but does not appear on the Figure.*

Response: The location of the proposed stockpile area is included in **Figure 8**.

Comment 6: *A plan should be included in the SARA to detail provisions to ensure that contaminated soils are not spread into uncontaminated areas. This includes trucks, truck tires, ingress and egress from the site and decontamination procedures. The exclusion zone should be secure through use of a fence or other measures to prevent access to the site.*

Response: Acknowledged. The SARA will include a plan to ensure that contaminated soils are not spread into uncontaminated areas.

Comment 7: *A stormwater runoff plan should also be included in the SARA. How will the stockpile be covered in the event of rainfall?*

Response: Acknowledged. A stormwater runoff plan will be included in the SARA.

Comment 8: *As previously stated, the leachability SCTL for arsenic should be determined to ensure that all soils that exceed the leachability SCTL are removed.*

Response: See response to comment 1 under Leachability SCTL for Arsenic above.

Comment 9: *No reference is made as to what fill material will be used to fill the excavation after the contaminated soil is removed.*

Response: The excavation area will be backfilled with certified clean fill.



PROPOSED GROUNDWATER MONITORING PLAN

Comment 1: *It is premature to propose a monitoring plan prior to completion of the SAR.*

Response: Acknowledged.

CONCLUSIONS


The above responses were prepared in order to provide the Department with information regarding additional investigations that will be conducted at the subject site. These responses were also prepared in anticipation of an upcoming meeting between representatives of Beazer Homes and the Department. The goal of the initial response is to present the rationale for proposed additional assessment activities and to provide proposed sampling locations.

HSA has previously presented a remedial approach for the subject site that will facilitate site redevelopment and valuable use of the subject site that was formerly operated as an executive golf course. The plan includes the use of engineering/institutional controls to prevent exposure of arsenic to future on-site residents. As we discussed, HSA (on behalf of Beazer Homes) is seeking written agency concurrence in the proposed remedial approach for the site no later than December 15, 2006. To that end we believe that the information presented above along with the proposed additional sampling activities are adequate for determining the nature and extent of contamination at the subject site for the Department to concur that the site assessment requirements under Chapter 62-780, FAC have been met.

We look forward to meeting with you on October 13, 2006, to discuss our responses in more detail and answer any questions you may have. In the meantime, feel free to contact us if you have any questions.


Sincerely,

HSA Engineers & Scientists




Brian Moore, P.E.

Environmental Program Manager



Nicholas Albergo, P.E. / DEE
Chairman



TABLES

Table 1
Summary of Arsenic Soil Analytical Data
Countryside Executive Golf Course, Clearwater, Florida
HAS Project Number 6015982-00

Depth (ft)	Sample ID									
	CSS-1	CSS-2	CSS-3	CSS-4	CSS-5	CSS-6	CSS-7	CSS-8	CSS-9	CSS-10
0 - 2' (a)	8/26/2004	8/26/2004	8/26/2004	8/26/2004	8/26/2004	8/26/2004	8/26/2004	8/26/2004	8/26/2004	8/26/2004
	2.1	1.6	1.2	8.6	3.1	2.7	9.0	8.3	3.2	5.1
Depth (ft)	Sample ID									
	CSS-11	CSS-12	CSS-13	CSS-14	CSS-15	CSS-16	CSS-17	CSS-18	CSS-19	CSS-20
0 - 2' (a)	10/4/2004	10/4/2004	10/5/2004	10/5/2004	10/5/2004	10/5/2004	10/5/2004	10/5/2004	10/5/2004	10/1/2004
	0.62	0.9	1.1	0.151	0.201	0.351	2.2	1.0	1.3	3.0
2' - 4' (b)	<0.14	0.351	0.181	<0.15	0.94	0.56	3.5	0.72	0.381	0.441
Depth (ft)	Sample ID									
	CSS-21	CSS-22	CSS-23	CSS-24	CSS-25	CSS-26	CSS-27	CSS-28	CSS-29	CSS-30
0 - 2' (a)	10/5/2004	10/1/2004	10/1/2004	10/1/2004	10/1/2004	10/1/2004	10/1/2004	10/1/2004	10/1/2004	10/1/2004
	9.2	7.2	1.6	2.7	5.9	7.9	2.6	7.2	9.8	9.9
2' - 4' (b)	0.311	0.69	0.351	0.451	3.3	0.231	1.4	0.301	0.41	0.72
Depth (ft)	Sample ID									
	CSS-31	CSS-32	CSS-33	CSS-34	CSS-35	CSS-36	CSS-37	CSS-38	CSS-39	CSS-40
0 - 2' (a)	10/1/2004	10/7/2005	10/7/2005	10/7/2005	10/7/2005	10/7/2005	10/7/2005	10/7/2005	10/7/2005	10/7/2005
	25	3.5	48	4.4	2.8	1.81	<0.63	7.9	6.8	13
2' - 4' (b)	0.281	3.0	<0.8	7.1	5.3	3.9	1.5	1.61	<0.76	1.5
Depth (ft)	Sample ID									
	CSS-41	CSS-42	CSS-43	CSS-44	CSS-45	CSS-46	CSS-47	CSS-48	CSS-49	CSS-50
0 - 2' (a)	10/7/2005	11/16/2004	11/16/2004	11/16/2004	11/16/2004	11/16/2004	11/15/2004	11/15/2004	11/15/2004	11/15/2004
	1.3	0.291	2.3	1.4	3.8	1.4	1.8	5.0	3.5	3.8
2' - 4' (b)	0.76	0.231	0.57	0.321	1.1	3.2	2.4	0.60	0.411	1.9
Depth (ft)	Sample ID									
	CSS-51	P1	P2	P3	P4	P5	P6			
0 - 2' (a)	11/15/2004	10/6/2004	10/6/2004	10/6/2004	10/6/2004	10/6/2004	10/6/2004			
	0.80	<0.72	<0.63	<0.76	<0.90	<0.75	0.711			
2' - 4' (b)	1.7	<0.66	<0.78	<0.67	<0.73	<0.72	<0.73			
4' - 6' (c)		<0.75	<0.75	<0.70	<0.73	<0.71	<0.68			
6' - 8' (d)		<0.65	<0.75	<0.76	<0.74	<0.64	<0.73			
8' - 10' (e)		<0.80	1.11	<0.72	<0.76	<0.75	<0.68			
10' - 12' (f)		<0.75	<0.78	<0.66	<0.69	<0.66	<0.74			
12' - 14' (g)		<0.75	<0.81	<0.76	<0.67	<0.72	<0.75			
14' - 16' (h)		<0.68	1.21	<0.67	<0.75	<0.64	<0.70			
Depth (ft)	Sample ID									
	SS-1	SS-2	SS-3	SS-4	SS-5	SS-6	SS-7	SS-8	SS-9	SS-10
0 - 6" (a)	7/5/2005	7/5/2005	7/5/2005	7/5/2005	7/5/2005	7/5/2005	7/5/2005	7/5/2005	7/5/2005	7/5/2005
	6.15	17.3	3.01	13	10.8	20.9	<0.391	4.24	11.9	13.1
6" - 2' (c)	6.26	1.59	<0.396	2.32	1.71	0.588	1.11	0.612	1.74	1.29
2' - 4' (e)	0.694	1.41	<0.288	5.23	<0.379	0.43	12.7	<0.308	2.2	<0.401
Depth (ft)	Sample ID									
	MW-2 East	MW-2 North	MW-2 West	MW-2 South						
0 - 6"	5/30/2006	5/30/2006	5/30/2006	5/30/2006						
	3.56	6.63	6.38	4.7						

Notes:

ft - feet

mg/kg - milligrams per kilogram

SCTL - Soil Cleanup Target Level as established in Chapter 62-777, Florida Administrative Code

Bold indicates exceedance of the Residential Direct Exposure SCTL of 2.1 mg/kg

Shade indicates exceedance of the Commercial/Industrial Direct Exposure SCTL of 12 mg/kg

NA - Not Analyzed

BDL - Below Detection Limits

Table 2

**Summary of Historical Arsenic Groundwater Analytical Data
Countryside Executive Golf Course, Clearwater, Florida
HSA Project Number 6015982-00**

	TW-1		TW-2		TW-3		TW-4		TW-5		TW-6									
Date	08/27/04	10/07/04	11/16/04	10/06/04	11/16/04	10/06/04	11/15/04	10/06/04	11/15/04	10/07/04	11/16/04	10/07/04								
Arsenic	470	620	180	15	8.21	100	23	87	75	330	540	8.4								
	TW-7		TW-8		TW-9		TW-10		TW-11		TW-12		TW-13		TW-14		TW-15		TW-16	
Date	10/07/04	01/13/05	11/15/04	11/15/04	11/15/04	11/15/04	11/15/04	11/15/04	11/15/04	6/13/2006	11/16/04	11/16/04	06/13/06	06/13/06	06/13/06	06/13/06	06/13/06	06/13/06	06/13/06	06/13/06
Arsenic	14	<2.8	3.51	4.41	<2.8	13	12	5.44	12	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5	<5
	DW-1				MW-1				MW-2				MW-3							
Date	07/14/05	08/01/05	08/26/05	11/07/05	08/26/05	6/5/2006	11/07/05	5/30/2006	6/13/2006	08/26/05	11/07/05	5/30/2006	6/13/2006	08/26/05	11/07/05	5/30/2006	6/13/2006	08/26/05	11/07/05	5/30/2006
Arsenic	17.6	12.4	15.2	<2.8	46.9	<5	130	37.3	79.8	159	5.4	159	5.4	159	5.4	159	5.4	159	5.4	159
	MW-4		MW-5		MW-6		MW-7		MW-8		MW-9		MW-10		MW-11		MW-12		MW-13	
Date	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05	08/26/05	11/07/05
Arsenic	87	<2.8	87	<2.8	87	<2.8	87	<2.8	87	<2.8	87	<2.8	87	<2.8	87	<2.8	87	<2.8	87	<2.8

Note:

Units given in micrograms per liter (µg/l).

I - Analyte detected below the quantitation limits.

Red indicates result exceeds Groundwater Cleanup Target Level (GCTL) of 10 µg/L as established in Chapter 62-777, Florida Administrative Code (FAC).

Blue indicates result exceeds Natural Attenuation Default Source Concentration (NADSC) of 100 µg/L as established in Chapter 62-777, FAC.

Table 3
Summary of Supplemental Analytical Data
Countryside Executive Golf Course, Clearwater, Florida
HSA Project Number 6015982-00

Sample ID	Date	Depth (ft bls)	Arsenic	Chlorinated Pesticides		Chlorinated Herbicides	
				Endosulfan I	All others	2,4'-D	All others
Soil Analytical Data							
			mg/kg	µg/kg	µg/kg	µg/kg	µg/kg
SCTL-Residential Exposure			2.1	450,000	-	770,000	-
SCTL-Commercial Exposure			12	7,600,000	-	13,000,000	-
SB-1	5/31/2006	0-0.5	-	17	BRL	<11	BRL
SB-2	5/31/2006	0-0.5	-	<1.6	BRL	<10	BRL
SB-3	5/31/2006	0-0.5	-	<1.6	BRL	<10	BRL
SB-4	5/31/2006	0-0.5	-	<1.6	BRL	21	BRL
Sediment Composite	5/30/2006	-	3.1	<1.9	BRL	-	-
MW-2 East	5/30/2006	0-0.5	3.56	-	-	-	-
MW-2 South	5/30/2006	0-0.5	4.7	-	-	-	-
MW-2 North	5/30/2006	0-0.5	6.63	-	-	-	-
MW-2 West	5/30/2006	0-0.5	6.38	-	-	-	-
Groundwater Analytical Data							
			µg/L	µg/L	µg/L	µg/L	µg/L
GCTL			10	42	-	70	-
FSWC			50	0.056	-	80	-
MW-1R	6/5/2006	2-12	<5	-	-	-	-
MW-2	5/30/2006	2-12	37.3	-	-	-	-
	6/13/2006	2-12	79.8	-	-	-	-
TW-12	6/13/2006	2.25-12.25	5.44	-	-	-	-
TW-14	6/13/2006	2-12	<5				
TW-15	6/13/2006	2-12	<5				
TW-16	6/13/2006	2-12	<5				
Surface Water	5/30/2006	-	152	<0.051	BRL	-	-
	6/13/2006	-	49	-	-	-	-

Notes:

ft bls - feet below land surface

SCTL - Soil Cleanup Target Level as established in Chapter 62-777, Florida Administrative Code (FAC)

GCTL - Groundwater Cleanup Target Level as established in Chapter 62-777, FAC

FSWC - Freshwater Surface Water Criteria as established in Chapter 62-777, FAC

2,4'-D - 2,4-dichlorophenoxy acetic acid

mg/kg - milligrams per kilogram

µg/L - micrograms per liter

mg/L - milligrams per liter

- - Compound not analyzed for specific analyte


BRL - Below laboratory reporting limit

Bold indicates that the default Residential SCTL or the default GCTL was exceeded.



FIGURES

- LEGEND**
- ABOVEGROUND STORAGE TANK LOCATION
 - SOIL SAMPLE LOCATIONS (CSS-1-CSS-10) TAKEN AUGUST 26, 2004
 - SOIL SAMPLE LOCATIONS (CSS-11-CSS-41) TAKEN OCTOBER 1-7, 2004
 - SOIL SAMPLE LOCATIONS (P-1-P-6) TAKEN OCTOBER 1-7, 2004
 - SOIL SAMPLE LOCATIONS (SS-1-SS-10) TAKEN JULY 5, 2005



COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA

HSA
ENGINEERS & SCIENTISTS
4019 E. Fowler Avenue Tampa, Florida 33617
Tel: (813) 971-3882

DESIGNED	N/A	JOB NO.:	601598200
DRAWN	SBW	DATE:	10/3/06
CHECKED	BM	CAD NO.:	598200-1A
SHEET TITLE			
HISTORICAL SOIL SAMPLING LOCATIONS MAP			
FIGURE 1A			


G:\DESIGN\HSA-Drafting\60 Environmental\2005\Countryside Executive Center 6015892\october\589200-01



LEGEND

- MW-2 (TEMPORARY MONITOR WELL LOCATIONS (WHITE TEXT))
- MW-2 (SOUTH) (SOIL BORING LOCATION (WHITE TEXT) (MAY 2006))
- TW-14 (PROPOSED MONITOR WELL LOCATIONS)
- (PROPOSED SOIL BORING LOCATION)

FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
OCT - 4 2006
SOUTHWEST DISTRICT
TAMPA



COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA


HSA
ENGINEERS & SCIENTISTS
4019 E. Fowler Avenue Tampa, Florida 33617
Tel: (813) 971-3882

DESIGNED	JOB NO:	601598200
DRAWN	N/A	
CHECKED	DATE:	10/3/06
BM	CAD NO:	598200-1B

SHEET TITLE
MONITORING WELL
MW-2 AND
VICINITY

FIGURE 1B

G:\DESIGN\HSA-Drafting\60 Environmental\2005\Countryside Executive Center 6015892\October\589200-02



COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA

HSA
ENGINEERS & SCIENTISTS

JOB NO.: 601598200
DATE: 10/3/06
CAD NO.: 598200-02


DESIGNED N/A
DRAWN SBW
CHECKED BM

SHEET TITLE
SOIL ARSENIC
CONCENTRATIONS
(0-6")

FIGURE 2

4019 E. Fowler Avenue Tampa, Florida 33617
Tel: (813) 971-3882

G:\DESIGN\HSA-Drafting\60 Environmental\2005\Countryside Executive Center 6015892\October\589200-03



LEGEND

- SOIL SAMPLE LOCATIONS (SS-1-SS-10)
TAKEN JULY 5, 2005
- (<0.396) ARSENIC CONCENTRATION IN mg/kg
- mg/kg MILLIGRAMS PER KILOGRAM
- (RED) DENOTES VALUES WHICH EXCEED THE 2.1 mg/kg SOIL
CLEANUP TARGET LEVEL (SCTL) PER CHAPTER 62-777 F.A.C.

NOTE: SAMPLE DEPTH TAKEN AT 6 INCHES-2 FEET BELOW LAND SURFACE

FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
OCT - 4 2006
SOUTHWEST DISTRICT
TAMPA

01589200

N/A

10/3/06

589200-03

DESIGNED

DRAWN

CHECKED

DATE

DATE

DATE

DATE

DATE

DATE

0

150

300

450

600

SCALE: 1" = 300'±

COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA

HSA

ENGINEERS & SCIENTISTS

4019 E. Fowler Avenue
Tampa, Florida 33617
Tel: (813) 971-3882

JOB NO.: 601589200

DATE: 10/3/06

CAD NO.: 589200-03

DESIGNED

DRAWN

CHECKED

DATE

DATE

DATE

DATE


DATE

DATE

SOIL ARSENIC
CONCENTRATIONS
(6"-2')

FIGURE 3

G:\DESIGN\HSA-Drafting\60 Environmental\2005\Countryside Executive Center 6015892\October\589200-04




COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA

HSA
ENGINEERS & SCIENTISTS
4019 E. Fowler Avenue Tampa, Florida 33617
Tel: (813) 971-3862

JOB NO.:	601598200
DATE:	10/3/06
CAD NO.:	598200-04
DESIGNED	N/A
DRAWN	SBW
CHECKED	BM
SHEET TITLE SOIL ARSENIC CONCENTRATIONS (2'-4')	
FIGURE 4	

- LEGEND**
- SOIL SAMPLE LOCATIONS (P-1-P-6)
TAKEN OCTOBER 1-7, 2004
 - (<0.75) ARSENIC CONCENTRATION IN mg/kg
 - mg/kg MILLIGRAMS PER KILOGRAM
 - (RED) DENOTES VALUES WHICH EXCEED THE 2.1 mg/kg SOIL
CLEANUP TARGET LEVEL (SCTL) PER CHAPTER 62-777 F.A.C.

NOTE: SAMPLE DEPTH TAKEN AT 4 FEET-6 FEET BELOW LAND SURFACE



FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
OCT - 4 2006
SOUTHWEST DISTRICT
TAMPA

COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA

HSA
ENGINEERS & SCIENTISTS
4019 E. Fowler Avenue Tampa, Florida 33617
Tel: (813) 971-3862

DESIGNED	N/A	JOB NO.: 601598200
DRAWN	SBW	DATE: 10/3/06
CHECKED	BM	CAD NO.: 598200-05
SHEET TITLE		
SOIL ARSENIC CONCENTRATIONS (4'-6')		
FIGURE 5		

- LEGEND**
- SOIL SAMPLE LOCATIONS (CSS-1-CSS-10)
TAKEN AUGUST 26, 2004
 - SOIL SAMPLE LOCATIONS (CSS-11-CSS-41)
TAKEN OCTOBER 1-7, 2004
 - SOIL SAMPLE LOCATIONS (P-1-P-6)
TAKEN OCTOBER 1-7, 2004
 - SOIL SAMPLE LOCATIONS (SS-1-SS-10)
TAKEN JULY 5, 2005
 - ⊙ PROPOSED SOIL SAMPLE LOCATION




FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
OCT - 4 2006
SOUTHWEST DISTRICT
TAMPA

COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA

HSA
ENGINEERS & SCIENTISTS
4019 E. Fowler Avenue Tampa, Florida 33617
Tel: (813) 971-3882

DESIGNED	N/A	JOB NO.:	601598200
DRAWN	SBW	DATE:	10/4/06
CHECKED	BM	CAD NO.:	598200-02
SHEET TITLE PROPOSED SITE-WIDE DELINEATION SOIL SAMPLING LOCATIONS			
FIGURE 6			



FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
OCT - 4 2006
SOUTHWEST DISTRICT
TAMPA

LEGEND

- TEMPORARY MONITOR WELL LOCATIONS (TW-1-TW-3)
INSTALLED AUGUST 27, 2004
- ▲ TEMPORARY MONITOR WELL LOCATIONS (TW-4-TW-7)
INSTALLED OCTOBER 6, 2004
- MONITOR WELL LOCATION (MW-1-MW-4)
INSTALLED AUGUST 16, 2005
- SURFACE WATER/SEDIMENT SAMPLE LOCATION
- ▲ TEMPORARY MONITOR WELL LOCATIONS (TW-14-TW-16)
INSTALLED JUNE 13, 2006



0 175 350 525 700
SCALE: 1" = 350'±

COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA

HSA
ENGINEERS & SCIENTISTS

4019 E. Fowler Avenue Tampa, Florida 33617

Tel: (813) 971-3882

DESIGNED	JOB NO:	601598200
DRAWN	N/A	
CHECKED	DATE:	10/3/06
	CAD NO:	598200-07
SHEET TITLE		
SITE-WIDE MONITORING WELL LOCATION PLAN		
FIGURE 7		


Z:\DESIGN\HSA-Drafting\60 Environmental\2006 Countryside Executive Center 6015892\OCTOBER\589200-08




FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
OCT - 4 2006
SOUTHWEST DISTRICT
TAMPA

LEGEND


- AST ■ ABOVEGROUND STORAGE TANK LOCATION
- TEMPORARY MONITOR WELL LOCATIONS (TW-1-TW-3) INSTALLED AUGUST 27, 2004
- ▲ TEMPORARY MONITOR WELL LOCATIONS (TW-4-TW-7) INSTALLED OCTOBER 6, 2004
- TEMPORARY MONITOR WELL LOCATIONS (TW-8-TW-13) INSTALLED NOVEMBER 12, 2004
- DEEP MONITOR WELL LOCATION (DW-1) INSTALLED JULY 5, 2005
- APPROXIMATE EXTENT OF ARSENIC GROUNDWATER IMPACTS ABOVE THE GROUNDWATER CLEAN UP TARGET LEVEL (GCTL) AS ESTABLISHED IN CHAPTER 62-777, F.A.C.



COUNTRYSIDE EXECUTIVE GOLF COURSE
2506 COUNTRYSIDE BOULEVARD
CLEARWATER, FLORIDA





JOB NO.:	601589200	CAD NO.:	589200-08
DESIGNED	N/A	DRAWN	SBW
DATE:	10/3/06	CHECKED	BM
SHEET TITLE			
SOIL EXCAVATION PLAN			
FIGURE 8			



APPENDIX A

PRO-UCL Calculation Summary Sheets

FDEP UCL Calculator Version 1.0
Goodness-of-fit test results



Shapiro-Francia Results (Adjust for Censoring)

SF for Normal Distribution 0
SF for LogNormal Distribution 0
Shapiro-Francia critical value for $p < 0.05$ 0.93888

Test stat > critical value indicates a reasonable fit

Shapiro-Wilk's Test Results for All Data (BDL replaced with 1/2 DL)

SW test statistic for Normal Distribution 0.581
SW test statistic for LogNormal Distribution 0.969
Shapiro-Wilk's critical value for $p < 0.05$ 0.874

Test stat > critical value indicates a reasonable fit

Based on the results of the Shapiro-Wilk's test
Distribution is best described as: Lognormal

Lognormal

FDEP UCL Calculator Version 1.0

10/3/06

Summary Statistics for Date (0-2)

Number of Samples	14
Number of Censored Data	2
Minimum	0.315
Maximum	48
Mean	7.735357
Median	3.95
Standard Deviation	12.21318
Variance	149.1618
Coefficient of Variation	1.578877
Skewness	3.131968

95% UCL (Assuming Normal Data)

Student's-t	13.51587
-------------	----------

95% UCL (Adjusted for Skewness)

Adjusted-CLT	16.02469
Modified-t	13.97124

95% Non-parametric UCL

CLT	13.10482
Jackknife	NA
Standard Bootstrap	13.06411
Bootstrap-t	22.16494
Chebyshev (Mean, Std)	21.96361

Summary Statistics for ln(Date (0-2))

Minimum	-1.15518
Maximum	3.871201
Mean	1.214403
Standard Deviation	1.406869
Variance	1.979279

Goodness-of-Fit Results

Distribution Recommended	Lognormal
Distribution Used	Lognormal

Estimates Assuming Lognormal Distribution

MLE Mean	9.061574
MLE Standard Deviation	22.63131
MLE Median	3.368283
MLE Coefficient of Variation	2.497504

MVUE Estimate of Mean	7.899206
MVUE Estimate of Std. Dev.	13.19611
MVUE Estimate of SE	3.507048
MVUE Coefficient of Variation	1.670561



UCL Assuming Lognormal Distribution

95% H-UCL	37.76412
95% Chebyshev (MVUE) UCL	23.18608
99% Chebyshev (MVUE) UCL	42.79398

FDEP Recommended UCL to Use:

21.96361

FDEP UCL Calculator Version 1.0
Goodness-of-fit test results



Shapiro-Francia Results (Adjust for Censoring)

SF for Normal Distribution 0
SF for LogNormal Distribution 0
Shapiro-Francia critical value for $p < 0.05$ 0.929337

Test stat > critical value indicates a reasonable fit

Shapiro-Wilk's Test Results for All Data (BDL replaced with 1/2 DL)

SW test statistic for Normal Distribution 0.842
SW test statistic for LogNormal Distribution 0.934
Shapiro-Wilk's critical value for $p < 0.05$ 0.859

Test stat > critical value indicates a reasonable fit

Based on the results of the Shapiro-Francia test
Distribution is best described as: Neither

Neither

FDEP UCL Calculator Version 1.0

10/3/06

Summary Statistics for Date (2-4)

Number of Samples	12
Number of Censored Data	3
Minimum	0.335
Maximum	7.1
Mean	2.289583
Median	1.55
Standard Deviation	2.147894
Variance	4.613448
Coefficient of Variation	0.938116
Skewness	1.28649

95% UCL (Assuming Normal Data)

Student's-t	3.403109
-------------	----------

95% UCL (Adjusted for Skewness)

Adjusted-CLT	3.555639
Modified-t	3.441488

95% Non-parametric UCL

CLT	3.309555
Jackknife	NA
Standard Bootstrap	3.305811
Bootstrap-t	4.018563
Chebyshev (Mean, Std)	4.992353

Summary Statistics for ln(Date (2-4))

Minimum	-1.09362
Maximum	1.960095
Mean	0.387251
Standard Deviation	1.034024
Variance	1.069207

Goodness-of-Fit Results

Distribution Recommended	Neither
Distribution Used	Neither

Estimates Assuming Lognormal Distribution

MLE Mean	2.513949
MLE Standard Deviation	3.477135
MLE Median	1.472927
MLE Coefficient of Variation	1.383137

MVUE Estimate of Mean	2.320961
MVUE Estimate of Std. Dev.	2.548119
MVUE Estimate of SE	0.829322
MVUE Coefficient of Variation	1.097872

UCL Assuming Lognormal Distribution

95% H-UCL	6.65486
95% Chebyshev (MVUE) UCL	5.935894
99% Chebyshev (MVUE) UCL	10.57264



FDEP Recommended UCL to Use:

4.992353

Data for Maintenance Facility

Date (0-2)	Qualifier	Date (2-4)	Qualifier
9		3	
8.3		0.8 U	
3.5		7.1	
48		5.3	
4.4		3.9	
2.8		1.5	
1.8 J		1.6 J	
0.63 U		0.76 U	
7.9		1.5	
6.8		0.76	
13		1.7	
1.3		0.67 U	
0.8			
0.76 U			

FDEP UCL Calculator Version 1.0
Goodness-of-fit test results



Shapiro-Francia Results (Adjust for Censoring)

SF for Normal Distribution 0
SF for LogNormal Distribution 0
Shapiro-Francia critical value for $p < 0.05$ 0.975675

Test stat > critical value indicates a reasonable fit

D'Agostino's Test Results for All Data (BDL replaced with 1/2 DL)

Fit to Normal Distribution TRUE
Fit to LogNormal Distribution TRUE

Based on the results of the Shapiro-Wilk's test
Distribution is best described as: Lognormal

Lognormal

FDEP UCL Calculator Version 1.0

10/3/06

Summary Statistics for result (0-2)

Number of Samples	53
Number of Censored Data	4
Minimum	0.15
Maximum	9.9
Mean	3.215849
Median	2.3
Standard Deviation	2.807431
Variance	7.881666
Coefficient of Variation	0.872998
Skewness	0.95599

95% UCL (Assuming Normal Data)

Student's-t	3.86166
-------------	---------

95% UCL (Adjusted for Skewness)

Adjusted-CLT	3.904328
Modified-t	3.8701

95% Non-parametric UCL

CLT	3.850211
Jackknife	NA
Standard Bootstrap	3.898059
Bootstrap-t	4.114473
Chebyshev (Mean, Std)	4.896811

Summary Statistics for ln(result (0-2))

Minimum	-1.89712
Maximum	2.292535
Mean	0.688698
Standard Deviation	1.104607
Variance	1.220157

Goodness-of-Fit Results

Distribution Recommended	Lognormal
Distribution Used	Lognormal

Estimates Assuming Lognormal Distribution

MLE Mean	3.664809
MLE Standard Deviation	5.662953
MLE Median	1.991121
MLE Coefficient of Variation	1.545224

MVUE Estimate of Mean	3.594456
MVUE Estimate of Std. Dev.	5.160426
MVUE Estimate of SE	0.684229
MVUE Coefficient of Variation	1.435662

UCL Assuming Lognormal Distribution

95% H-UCL	5.319623
95% Chebyshev (MVUE) UCL	6.576944
99% Chebyshev (MVUE) UCL	10.40247

FDEP Recommended UCL to Use:

4.896811

Data set for Outside Maintenance Area

result (0-2)	qualifier	result (2-4)	qualifier
2.1		0.14	U
1.6		0.35	J
1.2		0.18	J
8.6		0.15	U
3.1		0.94	
2.7		0.56	
8.3		3.5	
3.2		0.72	
5.1		0.38	J
0.62		0.44	J
0.9		0.31	J
1.1		0.69	
0.15	J	0.35	J
0.2	J	0.45	J
0.35	J	3.3	
2.2		0.23	J
1		1.4	
1.3		0.3	J
3		0.4	J
9.2		0.72	
7.2		0.23	J
1.6		0.57	
2.7		0.32	J
5.9		1.1	
7.9		3.2	
2.6		2.4	
7.2		0.6	
9.8		0.41	J
9.9		1.9	
0.29	J	1.7	
2.3		0.66	U
1.4		0.78	U
3.8		0.73	U
1.4		0.72	U
1.8		0.73	U
5		0.694	
3.5		1.41	
3.8		0.288	U
0.8		5.23	
0.72	U	0.379	U
0.63	U	0.43	
0.9	U	12.7	
0.75	U	0.308	U
0.71	J	2.2	
6.23		0.401	U
5.52			
1.05			
3.98			
5.67			
0.93			
1.52			
4.28			
4.24			



APPENDIX B

Revised Well Completion Reports





MONITORING WELL COMPLETION REPORT

Project Name Countryside Project Number 601-5982 Date Installed 6/5/2006 Well # MW-1R
 Installation Supervised by J. Gravelle Well Location Replacement for MW-1
 Ground Elevation NM Water Level Measurement From Top of Casing _____
 Well Development Data until clear Method Peristaltic Pump Volume Purged 2 gallons
 Drilling Method Hand Auger Top of Casing Elevation (Measuring Point) 5.08
 Driller HSA Well Head Finish Type A ☐ B ☒ C ☐

A: Concrete Pad with Locking Protective Cover

B: Concrete Pad with Locking Cap - No protective Cover

C: Flush - Steel Manhole with Locking Cap



Depth (ft.)	SOIL PROFILE
1-6"	Grass with roots
6"-6'	grayish brown fine sand
6-12'	gray/brown silty fine sand




MONITORING WELL COMPLETION REPORT

Project Name Countryside Project Number 601-5982 Date Installed 6/13/2006 Well # TW-14
 Installation Supervised by C. Krieter Well Location east of MW-2
 Ground Elevation NM Water Level Measurement From Top of Casing _____
 Well Development Data until clear Method Peristaltic Pump Volume Purged 1.5 gallons
 Drilling Method Hand Auger Top of Casing Elevation (Measuring Point) 8.34
 Driller HSA Well Head Finish Type A ☐ B ☒ C ☐

A: Concrete Pad with Locking Protective Cover

B: Concrete Pad with Locking Cap - No protective Cover

C: Flush - Steel Manhole with Locking Cap



Depth (ft.)	SOIL PROFILE
1-6"	Grass with roots
6"-6'	brown fine sand
6-12'	gray/brown silty fine sand





MONITORING WELL COMPLETION REPORT

Project Name Countryside Project Number 601-5982 Date Installed 6/13/2006 Well # TW-16
 Installation Supervised by C. Krieter Well Location southeast of MW-1
 Ground Elevation NM Water Level Measurement From Top of Casing 7.6
 Well Development Data until clear Method Peristaltic Pump Volume Purged 2 gallons
 Drilling Method Hand Auger Top of Casing Elevation (Measuring Point) _____
 Driller HSA Well Head Finish Type A ☐ B ☒ C ☐

A: Concrete Pad with Locking Protective Cover

B: Concrete Pad with Locking Cap - No protective Cover

C: Flush - Steel Manhole with Locking Cap



Depth (ft.)	SOIL PROFILE
1-3"	Grass with roots
3"-4'	brown fine sand
4-8'	grayish brown silty fine sand
8-12'	brown fine sand
Seal Type	
30/65 Sand	
Filter Pack Type	
20/30 silica	
Screen Type	
0.010-slot	